

Lower level inside the north entrance.



This doorway was revealed when walls on the east side of the stairway leading to the lowest level from the south entrance of the building were removed. It is likely that this was a main entrance to the building when only the original east half of the building was in existence. Inside the door, remnants of a staircase can be seen.



This space was most recently occupied by the business office.



This space was most recently the president's office.



Monthly Update

Old Main Renovation

January 2025



Interior demolition underway

Interior demolition is well underway in the Old Main renovation project. At this point, 90% of the lower level and 80% of the 1st floor demolition is complete. In this month's update, take a look at what's happening inside those walls as crews work hard toward the goal of renovating Old Main to provide a beautiful facility that will serve the students of the 21st century well.



The spiral staircase located backstage in the Old Main Theatre.



A view of the south entrance to the building taken from the first floor.

Campus Center elevator progress

Elevator installation is on schedule for completion the week of January 27, with completion of the full project planned for the following week.

www.mayvillestate.edu/oldmain